

alcoholix

Umgerüstete Fahrzeuge

Stand: 10.09.2008

Hersteller	Modell	Jahrgang	KW	Hubraum in L	Besonderheiten	TÜV
Alfa Romeo	33	1993	65	1,6	30/100-22-30	
Alfa Romeo	156	1997	88	1,6	30/100-22-30	
Alfa Romeo	166 3.0 V6	1999	166	3,0	30/100-22-30	
Audi	A4	2001	162	3,0		
Audi	A6	1993	128	2,7		
Audi	A8	1997	250	4,2		
BMW	Z3	1997	103	1,8		
BMW	316	1997	88	1,6		
BMW	323	2001	125	2,3		
Citroen	Xsara	2000	85	1,8	extra Stecker	
Citroen	Xsara	2002	100	2,0	Spule 2 x 3.9	
Dacia	Logan	2005	55	1,4		
Dacia	Logan 16V	2007	77	1,6	Spule 2 x 3.9	
Daewoo	Espero	1995	77	2,0		
Daewoo	Lacetti	2005	90	1,8	Spule 2 x 3.9	
Daewoo	Kalos	2005	69	1,4	Spule 2 x 3.9	
Dodge / Chrysler	Crossfire 3.2 V6	2006	160	3,2		
Dodge / Chrysler	PT Cruiser	2001	104	2,0	ex. Stecker, Spule 680	
Dodge / Chrysler	Wrangler	2007	146	3,7	löten, Spule 2 x 3.9	§21
Dodge / Chrysler	Ram 4.7 V8	2002	176	4,7	ex. Stecker, Spule 2 x 3.9	§21
Dodge / Chrysler	Charger RT	2006	246	5,7	ex. Stecker, Spule 680	§21
Dodge / Chrysler	SRT-8	2006	316	6,1	ex. Stecker, Spule 680	§21
Dodge / Chrysler	SRT-10 8.3 V10	2005	372	8,1	ex. Stecker, Spule 680	§21
Dodge / Chrysler	RAM 5.7 HEMI	2008	246	5,7	ex. Stecker, Spule 2 x 3.9	§21
Dodge / Chrysler	Grand Cherokee SRT-8	2008	316	6,1	ex. Stecker, Spule 2 x 3.9	§21
Fiat	Brava 1.6	2001	76	1,6		
Ford	Fiesta 1.1	2001	55	1,1		
Ford	Focus 1.6	2004	74	1,6		
Ford	Focus 1.8	1998	85	1,8		
Ford	Mondeo 2.0	1999	96	2,0		
Ford	Edge V6	2007	195	3,5	extra Stecker	
Ford	Mustang 4.0 V6	2005	151	4,0	extra Stecker	
Ford	Mustang GT V8	2006	220	4,6	extra Stecker	
Ford	F 150	2007	224	5,4	extra Stecker	
GM	Blazer	1999	142	4,3	löten	
GM	SSR 5.3 V8	2003	224	5,3	extra Stecker	
GM	Silverado SS 6.0	2005	250	6,0	extra Stecker	
GM	Escalade 6.0	2003	254	6,0	extra Stecker	
GM	Hummer H2	2008	316	6,2	extra Stecker	
Honda	Civic 1.4	2002	66	1,4	extra Stecker	
Hyundai	Accent	2000	55	1,4		
Kia	Sportage	1995	94	2,0		
Lada	Niva	2008	60	1,7		
Mazda	121	1992	53	1,2	Druckregler	

Hersteller	Modell	Jahrgang	KW	Hubraum in L	Besonderheiten	TÜV
Mercedes Benz	C 180	1997	90	1,8		
Mercedes Benz	E200	1998	100	2,0		
Mercedes Benz	S 320	2001	145	3,2		
Mercedes Benz	SL 320	1998	170	3,2		
Mercedes Benz	CL 500	2001	225	5,0		
Mitsubishi	Pajero	1999	130	3,0	Spule 680, löten	
Mitsubishi	Lancer Evo	2005	195	2,0		
Opel	Astra	1999	55	1,6	SPI Druckregler	
Opel	Corsa	2007	59	1,2		§21
Opel	Astra	2000	62	1,6		§21
Opel	Astra	2003	76	1,6		§21
Opel	Zafira	2003	74	1,6		§21
Opel	Vectra 1.8	1997	85	1,8	extra Stecker	§21
Opel	Omega 3,0 V6	1995	155	3,0	extra Stecker	§21
Peugeot	1007	2006	54	1,3	extra Stecker	
Peugeot	406	1996	97	2,0	Funktioniert nicht !!!	
Peugeot	406	1996	89	2,0	Spule 2 x 3.9	
Porsche	Boxter	2001	185	3,2	ca. 8 Std. Montage	
Renault	Clio 1.2 16 V	2002	55	1,2		
Renault	Megane	2006	99	2,0		
Renault	Trafic	2007	86	2,0		
Saab	9-3	2003	110	2,0		
Skoda	Fabia 1.4	2001	44	1,4	Spule 2 x 3.9	
Skoda	Superb V6	2004	146	2,8		
Smart	For Two	2003	52	0,6	30/100-22-30	
Smart	For Two	2006		0,7	30/100-22-30	
Suzuki	Jimny	2006	63	1,3	extra Stecker	§21
Suzuki	Swift	2007	68	1,3	extra Stecker	§21
Toyota	Van	1995	97	2,4	25/60-0-30	
Toyota	Yaris	1999	50	1,3	extra Stecker	
Volkswagen	Polo 86C	1992	40	1,2	SPI Druckregler	
Volkswagen	Polo	1996	44	1,2		
Volkswagen	Golf III 4 Zyl. 2.0	1994	85	2,0	1x Düse 2 Ohm	
Volkswagen	Passat	1996	85	2,0		
Volkswagen	T4	1993	81	2,4	1x Düse 2 Ohm	
Volkswagen	Passat VR 6	1996	128	2,8		
Volvo	V40	1998	85	1,8		